



# Government of Karnataka

Supporting Documentation for implementation of Ease of Doing Business Reforms in the State of Karnataka

**Concerned Department:** Factories and Boilers

**Area 6(d):** Renewal of License under the Indian Boiler Act, 1927

**DIPP Recommendation No. 162:** Design and implement a system that allows online application, payment, tracking and monitoring without the need for a physical touch point for document submission and verification.

Response: Yes

## Compliance Report

URL*	<a href="http://164.100.133.11:9080/FBIS/">http://164.100.133.11:9080/FBIS/</a>
G.O./Notification/ Act	-
Screenshots	Attached Annexures
Compliance Reform	e-surakshate website of the Department of Factories and Boilers provide a fully online system for entrepreneurs to apply, pay fees, track and monitor their license. This is verified by the Boiler Inspector or other designated authority through appropriate logins

*\*If the link does not open directly (when clicked), please copy paste the URL into browser address bar.*

### Step 1: User Login:



### Step 2: Select link for issue of Economizer:



### Step 3: Enter type and taluk :

164.100.133.11:9080/FBIS/CircleDivisionI.jsp

Government of Karnataka  
Department of Factories, Boilers, Industrial Safety & Health

Welcome demo Log out

**Select Taluk/Division:**

Select Heating Surface*	BELOW 10,000 Sq.mts
Select Taluk*	Bangalore
Division*	Senior Assistant Director of Boilers, Bangalore Division-1

Selecting the appropriate options

## Step 4: Fill the application and attach mandatory documents :

164.100.133.11:9080/FBIS/formjretrive?bxtreg=T-5997&getdetailss=Get+Details

### Particulars to be filled for generation of Form J

1. Registered No. of Boilers/Economiser\*  [Get Details](#) Example: KTK-9999

2. Boiler Type\*

3. Full name of the Owner\*

4. Full postal address and situation of the factory

Address\*  Pincode\*

Post\*

Taluk\*  Landline

District\*  Email\*

Mobile No\*

5. Date of inspection desirable\*  (Note- Inspection date should not be more than 15 Working days from date of application and it should be inline with certificate expiry date)

Click here if inspection date is a Holiday or Sunday

6. Description of Boiler & Age\*

Type\*  Boiler Rating\*  Sq.mts [Fee Calculator](#)

Place and Year of Make\*

---

164.100.133.11:9080/FBIS/formjretrive?bxtreg=T-5997&getdetailss=Get+Details

Steam Pipe Line Length Less than 100NB

Steam Pipe Line Length More than 100NB

8. Boiler and Steam Pipe Line Fee Details

For Boiler

Steam Pipe Line Upto 100NB

Steam Pipe Line Above 100NB

9. Fee paid details

Fee paid at\*  Challan No\*

Rs\*  Rupees(Amount in words)\*

and date\*

[You Can Also Pay the amount through online Payment gateway - Khajane-2](#)

Block K & L.pdf  FEE PAID CHALLAN IN ORIGINAL

Note :- Please upload the file in .jpg/.jpeg/.pdf format and the file size should not exceed 1MB

(Name of the Owner or Agent)\*

Date

Ergo Care Application running in the background...


14:33 14-07-2016

## Business Reform Action Plan **Step 5: You are successfully registered :**




Click and print the forms

## Step 6: Verifier Login:




Using Login credentials for Verifier to verify the form inputted

**Step 7: Select type of application :**



**Step 8: Click the submitted forms :**



# Business Reform Action Plan

Government of Karnataka  
Department of Factories, Boilers, Industrial Safety & Health

Welcome verifier

Application Status of the designated company is viewed

One item found. 1

FactId	Boiler Type	Reg.Boiler no	Owner name	Inspection Date	Boiler desc	Submitted Date
<a href="#">BER_14072016_002695F1</a>	Package Boiler	T-5997	M/s. Venkateswara Industries	2016-07-04	Pune - 1997	2016-07-14 14:34:47.49

[Back](#)

FORM 'J'	
Application for the Inspection of Boilers and Steam pipes under the Indian Boilers Act. 1923 (Act V 1923) (Vide Rule 26 of Karnataka Boiler Rules, 1982)	
1. Boilers Type	PACKAGE BOILER
2. Registered No. of Boilers/Economiser/steamline	T-5997
3. Name of the Owner	M/S. VENKATESWARA INDUSTRIES
4. Full postal address and situation of the factory	SINDHANUR ROAD, SIRUGUPPA - 583121, BELLARY DIST., Pincode: 583121  Phone:  Email Id: SA@GMAIL.COM
5. Date of inspection desirable	04/07/2016
6. Description of Boiler & Age	Type:HMT Boiler Rating:91 Place and Year of Make:PUNE - 1997
I hereby submit application to the Senior Assistant Director of Boilers, Bangalore Division-1 for inspection and the grant of a certificate for the Boiler above named, together with the treasury receipt in original obtained on payment of the prescribed fee	

	BELLARY DIST., Pincode: 583121  Phone:  Email Id: SA@GMAIL.COM
5. Date of inspection desirable	04/07/2016
6. Description of Boiler & Age	Type:HMT Boiler Rating:91 Place and Year of Make:PUNE - 1997
I hereby submit application to the Senior Assistant Director of Boilers, Bangalore Division-1 for inspection and the grant of a certificate for the Boiler above named, together with the treasury receipt in original obtained on payment of the prescribed fee specified above.	
Fee paid at SBI Rs 4450 (Rupees) FOUR THOUSAND FOUR HUNDRED FIFTY ONLY Challan No. and date 05/07/2016 .This 14th Day of July 2016	

Signature of Owner or Agent  
( )

2 items found, displaying all items.1  
**AttachmentFormJ**  
Challan.pdf   
Form\_J\_14072016.pdf

Remarks here


VERIFIED

Viewing the Forms



# Business Reform Action Plan

## Step 9: Approver Login :



# Business Reform Action Plan

Government of Karnataka  
Department of Factories, Boilers, Industrial Safety & Health

Welcome Senior Assistant Director of Boilers, Bangalore Division-2

## Approver's Screen

- [Applications due for Generation of Inspection Notice - \(3\)](#)
- [Inspection Pending Applications - \(7\)](#)
- [Approved Applications - \(76\)](#)
- [Form J1 - Due for Generation - \(241\)](#)
- [Form L - Due for Generation - \(3\)](#)
- [Rejected Applications - \(21\)](#)
- [Repairs Suggested Applications - \(0\)](#)

Government of Karnataka  
Department of Factories, Boilers, Industrial Safety & Health

Welcome Senior Assistant Director of Boilers, Bangalore Division-2

Log out

**Due for Generation of Inspection Notice- In Basket**

items found, displaying all items.1

FactId	Boiler Type	Reg.Boiler no	Owner name	Boiler desc	Remark	Submitted Date	Inspection Date
<a href="#">BLR_14072016_002694FJ</a>	Package Boiler	KTK-3001	Denim Works -II	Pune	Verified OK	2016-07-14 12:27:40.803	2016-07-21
<a href="#">TUM_12072016_002672FJ</a>	Package Boiler	MYS-1778	Eshwari Rice Mill	Doddaballapura 1990	Verified OK	2016-07-12 12:07:15.23	2016-07-18
<a href="#">TUM_11072016_002655FJ</a>	Package Boiler	KTK-2785	Mahalakshmi Rice mill		Verified OK	2016-07-11 16:55:55.827	2016-07-20

Back

# Business Reform Action Plan

[Logout](#)

**FORM 'J'**  
**Application for the Inspection of Boilers and Steam pipes under the Indian Boilers Act, 1923 (Act V 1923)**  
**(Vide Rule 26 of Karnataka Boiler Rules, 1982)**

1.	Boilers Type	PACKAGE BOILER
2.	Registered No. of Boilers/Economiser/steamline	KTK-3001
3.	Name of the Owner	DENIM WORKS -II
4.	Full postal address and situation of the factory	N. F/48, KIADB INDL AREA, Pincode: 561203 Phone: Email Id: BHAT@GOKALDAS.COM
5.	Date of inspection desirable	21/07/2016
6.	Description of Boiler & Age	Type:HMT Boiler Rating:114 Place and Year of Make:PUNE

I hereby submit application to the Senior Assistant Director of Boilers,Bangalore Division-2 for inspection and the grant of a certificate for the Boiler above named, together with the treasury receipt in original obtained on payment of the prescribed fee specified above.

Fee paid at SBM, BENGALURU Rs 5250 (Rupees) FIVE THOUSAND TWO HUNDRED FIFTY ONLY Challan No 290 and date 12/07/2016 .This 14th Day of July 2016

[Logout](#)

Place and Year of Make:PUNE

I hereby submit application to the Senior Assistant Director of Boilers,Bangalore Division-2 for inspection and the grant of a certificate for the Boiler above named, together with the treasury receipt in original obtained on payment of the prescribed fee specified above.

Fee paid at SBM, BENGALURU Rs 5250 (Rupees) FIVE THOUSAND TWO HUNDRED FIFTY ONLY Challan No 290 and date 12/07/2016 .This 14th Day of July 2016

Signature of Owner or Agent  
( )

3 items found, displaying all items.1

**AttachmentFormJ**

Challan.jpg

Form\_J.pdf

Form\_J\_14072016.pdf

**Reject**

**Step 1:Generate and Send Notice of Inspection of Boiler /Economiser**

Serial No:

Planned date of Inspection

[Back to top](#)

Generation and viewing of form J

**Step 10: View generated License:**

The screenshot shows a web browser window with the URL <http://164.100.133.11:9080/FBIS/jsp/FormJ1Submitted.jsp>. The main content is a boiler inspection report form titled "FORM. J-1" with the number "No.133/2016-17". The form is titled "Boiler inspection Department, Karnataka Declaration of inspector (Vide Rule 27 of Karnataka Boiler Rules 1982)".

**FORM. J-1**  
No.133/2016-17  
**Boiler inspection Department, Karnataka Declaration of inspector**  
(Vide Rule 27 of Karnataka Boiler Rules 1982)

Date: 02/07/2016 Registration No.: KTK-3981  
Type of Boiler : HMT with W/W  
Owner and location : Magnesium & Allied Products  
S.N. 74/1B, Hurugalvadi Koppa Hobli

Purpose for which used : Chemicals  
Rating: 117 MT.Sq. Fees paid and date of payment: Rs.4500/- Dt. 01/07/2016  
Repairs carried out since last inspection : Nil. Last hydraulic pressure applied 15.0 KSCG on 02/07/2016. Last  
Maximum working pressure allowed 10.54 KSCG up to 01/07/2017 . On inspection of the boiler in the presence of  
Apparao Being Apparao , I make the following detailed observation :

1. Shell or drums	Satisfactory
2. The plates, Wrapper, fire door sheets etc	Satisfactory
3. Fire tubes or Water tubes	Satisfactory
4. Headers	Nil
5. Super Heaters	Nil
6. Flue and furnace	Satisfactory
7. Masonry, Lagging etc	Satisfactory

This screenshot shows the same boiler inspection report form as above, but with a "Print this page" button at the bottom. The form includes a more detailed list of observations.

Maximum working pressure allowed 10.54 KSCG up to 01/07/2017 . On inspection of the boiler in the presence of  
Apparao Being Apparao , I make the following detailed observation :

1. Shell or drums	Satisfactory
2. The plates, Wrapper, fire door sheets etc	Satisfactory
3. Fire tubes or Water tubes	Satisfactory
4. Headers	Nil
5. Super Heaters	Nil
6. Flue and furnace	Satisfactory
7. Masonry, Lagging etc	Satisfactory
8. Mountings	Satisfactory
9. Safety valve	Satisfactory
10. Pressure Gauge	Satisfactory
11. Quality of feed water	Softened water
12. Hydraulic pressure applied	15.0
13. Result of Hydraulic test	Satisfactory
14. Repairs found necessary	Nil
15. Remarks	Certified upto 01/07/2017

Encl : MI Book  
Date : 5/7/2016

Print this page

Print the form